Pontiac 2+2 Registry - Pontiac 2+2 Registry

Generated: 18 April, 2024, 18:23

1966 Catalina 2+2Posted by studelover - 2016/03/02 19:15

I am working on my 1966 2+2 Pontiac, I just installed the front Bumpers and one side the wrap around edge is sticking out. Do I have a bumper problem or a bracket problem? There are3 holes on the bumper edge I have bumper bolts going though 2 of the holes am I missing something there. http://www.pontiac2plus2registry.com/images/fbfiles/images/66revisited 2016 03 02 007.JPG Rodney

Re:1966 Catalina 2+2 Posted by studelover - 2016/03/04 20:13

There is a bracket that is not in the manual. It fits on the third bumper bolt. I have a 1966 Catalina in a junk yard near me. It has those brackets on the car, I got them yesterday before the snow.